


All information furnished regarding this property is from sources deemed reliable but no warranty or representation is made to the accuracy thereof. Purchaser to verify measurements if important.



FLOOR

MAIN

LOWER TOTAL





ORDERS@REALFOTO.CA MEASURED 04/04/2019 BY DAN VAN DER MERWE

All information furnished regarding this property is from sources deemed reliable but no warranty or representation is made to the accuracy thereof. Purchaser to verify measurements if important.

