


MAIN FLOOR



FLOOR	FINISHED	UNFINISHED	TOTAL	OTHER AREAS	
MAIN	905	0	905	CARPORT	183
UPPER	867	0	867	DECKS	364
LOWER	477	97	574	BALCONY	64
TOTAL	2249	97	2346	PATIO	322
				CRAWLSPACE	332



38216 SCHOONER WAY

DOCUMENT PREPARED FOR THE EXCLUSIVE USE OF

SCOTT GARMAN & MIKE GARMAN





ENGEL & VÖLKERS

250-388-6998
ORDERS@REALFOTO.CA

MEASURED 09/30/2019 BY KARA ANDERSON

All information furnished regarding this property is from sources deemed reliable but no warranty or representation is made to the accuracy thereof. Purchaser to verify measurements if important.

UPPER FLOOR



FLOOR	FINISHED	UNFINISHED	TOTAL	OTHER AREAS	
MAIN	905	0	905	CARPORT	183
UPPER	867	0	867	DECKS	364
LOWER	477	97	574	BALCONY	64
TOTAL	2249	97	2346	PATIO	322
				CRAWLSPACE	332



38216 SCHOONER WAY

DOCUMENT PREPARED FOR THE EXCLUSIVE USE OF

SCOTT GARMAN & MIKE GARMAN





ENGEL & VÖLKERS

250-388-6998
ORDERS@REALFOTO.CA

MEASURED 09/30/2019 BY KARA ANDERSON

All information furnished regarding this property is from sources deemed reliable but no warranty or representation is made to the accuracy thereof. Purchaser to verify measurements if important.

LOWER FLOOR



FLOOR	FINISHED	UNFINISHED	TOTAL	OTHER AREAS
MAIN	905	0	905	CARPORT 183
UPPER	867	0	867	DECKS 364
LOWER	477	97	574	BALCONY 64
TOTAL	2249	97	2346	PATIO 322 CRAWLSPACE 332



38216 SCHOONER WAY

DOCUMENT PREPARED FOR THE EXCLUSIVE USE OF

SCOTT GARMAN & MIKE GARMAN



ENGEL & VÖLKERS

250-388-6998
ORDERS@REALFOTO.CA

MEASURED 09/30/2019 BY KARA ANDERSON

All information furnished regarding this property is from sources deemed reliable but no warranty or representation is made to the accuracy thereof. Purchaser to verify measurements if important.